



Western Michigan University  
ScholarWorks at WMU

---

Legacy Scout Tickets from Pure Oil Company

---

8-20-2021

**MGRRE\_PureOilScoutTickets\_Curtis, Edna  
Comm.\_1\_21117080610000**

MGRRE  
*Western Michigan University*

Follow this and additional works at: <https://scholarworks.wmich.edu/pure>



Part of the Geology Commons

---

#### **WMU ScholarWorks Citation**

MGRRE, "MGRRE\_PureOilScoutTickets\_Curtis, Edna Comm.\_1\_21117080610000" (2021). *Legacy Scout Tickets from Pure Oil Company*. 6689.  
<https://scholarworks.wmich.edu/pure/6689>

This Document is brought to you for free and open access via ScholarWorks at WMU. It has been accepted for inclusion in Legacy Scout Tickets from Pure Oil Company by an authorized administrator of ScholarWorks at WMU. See the National Digital Catalogue - Science Base Catalogue for more collections submitted by MGRRE.



---

MGRRE\_PureOilScoutTickets\_Curtis, Edna Comm.\_1\_21117080610000

API 21117080610000

Permit Number 8061

Lease Name Curtis, Edna Comm.

Well Number 1

County Montcalm

Township 12N

Range 06W

Section 20

2021 DEQ or Pure co\_name Barber, Leslie T.

Pure Number 598

Latitude 43.41121

Longitude -85.04889

THE PURE OIL COMPANY

DATE October 2, 1940

## LOCATION REPORT

No. 598

STATE Michigan COUNTY Montcalm DIST. Home TWP. Home SEC. 20 TOWN 12<sup>N</sup> RANGE 6<sup>W</sup>  
 WELL No. 1 (SERIAL No. 598) FARM Edna Curtis (Comm.) ACRES 6<sup>W</sup>

NAME OF STREAM OR WATERS \_\_\_\_\_ QUADRANGLE NW SE SEOPERATOR Belvidere Oil Company Map Home Township, Montcalm County

Feet from North Line of Farm

1270 270

" " East " " "

1120/20

" " South " " "

" " West " " "

Feet from North Line of Section

1270 270" " East " 1 1/4 "1120/20

" " South " " "

" " West " " "

O LOCATION

① RIG

⊕ DRILLING

☼ GAS WELL

● OIL WELL

● SMALL OIL WELL

## LEGEND

⊙ DRY HOLE

● DRY SHOWING OIL


☼ DRY SHOWING GAS

⊙ ABANDONED LOCATION

☼ ABANDONED GAS WELL

● ABANDONED OIL WELL

NOTE: Below make tracing from map, (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location.



REMARKS:

SIGNED

W

Superintendent or Foreman.



D. C. Shackelford